## FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1.	Name of the Officer	ASSISTANT ENAMES
2.	Name of the School	ST- GREGORIOUS SCHOOL
3.	Location with name of Education District/ Sub. District	Mulakyzba, Marelitkara Dist.
4.	Classification of Building as specified in column 4 of the	chergannur sub district
		1. 45. 80 × 9 48 × 3-30 (RCC three storey building)
		2.73.14 x 9. 84x 3.60 m (RCC simile
5.	Period for which the certificate is issued	1-1-0
6.		222-23 1 1 1 min (hive block)
	a) Foundation and basement	022-23 Academic year
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up	>
	e) Roof	Note
	f) Flooring	
	g) Miscellaneous (Cracks, etc.)	
7.	Any major defects noticed which will render the building unsafe in any manner	NIL
8.	Whether maintenance works have been done properly	Y62-5
	Whether the structure is sound or not for conducting class	mestructure is sate for constructing classes
N	old . 1. The subling of the structure should be an animal	ed also with reference to location, altitude, intensity of wind, if deemed necessary for the certificate may be furnished
	0505	
	CERTII	FICATE
	certified that the school building was inspected by	me on 18/01/2022
found	to be fit / unfit to conduct classes, for the period	
	ons stated above.	(0.2.9.2.2.3
Place	Mulakuda (88055	
The second second	19-01-2002	Scall
300	1 00d 1 00d	
MULA	BRUZHY BY	- June
500/8-6-13	689-605 MANAGER	PRINCIPAL Assistant Engineer
0	ST. GREGORIOS SEN. SEC. SCHOOL MULAKUZHA, KERALA	ST. GREGORIOS SEN. SEC. SCHOOL: MULAKUZHA, KERALA
10	MOLANGENA, RENALA	The state of the s